



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office
Lease No. **SF-078622**
Unit
Luthy Federal

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	X
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

12/26, 19 61

Well No. 1 is located 1520 ft. from N line and 1820 ft. from E line of sec. 11

<u>SW/4 NE/4 Sec. 11</u> (1/4 Sec. and Sec. No.)	<u>26N</u> (Twp.)	<u>9W</u> (Range)	<u>NMPM</u> (Meridian)
<u>Undes. P.C. & Basin Dakota</u> (Field)	<u>San Juan</u> (County or Subdivision)	<u>New Mexico</u> (State or Territory)	

The elevation of the derrick floor above sea level is 6221 ft. G.L.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

12-11-61 - Spudded 1:00 P.M. Drid. 313' - Ran & set 9 jts. 286'
9 5/8" 32.30# surface casing @ 296' KB, cemented
w/250 sx regular 2% HA-5, plug down @ 1:30 PM 12/12/61
WOC 17 hrs. pressure test w/600# for 30 minutes
Drilling



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Southwest Production CompanyAddress 207 Petr. Club PlazaFarmington, New MexicoBy [Signature]Title Production Accountant