



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe ✓  
Lease No. SP 078933  
Unit J. W. Goddard

RECEIVED

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<u>Production</u> <u>X</u>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....	<u>Report of Perforations</u> <u>X</u>	
	<u>Report of Sand/Oil Fracing</u> <u>X</u>	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 6, 1958

J. W. Goddard  
Well No. 9 is located 1920 ft. from N line and 640 ft. from W line of sec. 11  
Sec. 11-11-11 Section 11 26N 12W N.M.P.M.  
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)  
Gallaga (Gallup) San Juan New Mexico  
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6052 ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Run & set  $5\frac{1}{2}$ " OD casing at 5234' & cemented w/125 sks. reg. cement & 114 sks. struts crete.  
Run Temperature Survey & found top of cement behind  $5\frac{1}{2}$ " OD casing at 4518'.

Perforated  $5\frac{1}{2}$ " OD casing 5130-66' w/4 Schlumberger bullets per ft., total 36', 144 shots.

Probed Gallup formation, down  $5\frac{1}{2}$ " OD casing, thru  $5\frac{1}{2}$ " OD casing perfs. 5130-66' w/40,000# of 20/40 sand & 40,320 gals. lvs. oil by Small. BHP 1700#. Max. TP 2900#, Min. TP 2400#. Inj. rate 50.1 BPH. Time of treatment 24 min. Standing press. in 10 min. 600#

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company \_\_\_\_\_

Address \_\_\_\_\_

NORTH OIL COMPANY

P.O. Box 100

Gallup, New Mexico

By \_\_\_\_\_

Title District Superintendent