UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

	and the second of the second o		
Sundry Noti	ces and Reports on Wells		
		5.	Lease Number SF-078388
1. Type of Well GAS	100 MOV 1 / 103	6.	
2. Name of Operator BURLINGTON	671 CO	7.	Unit Agreement Name
DECOUDER	& GAS COMPANY		
		8.	
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700		9.	HUERFANITO UNIT 64 API Well No. 300450596200
4. Location of Well, Footage, Sec., T, R, M 900' FNL, 1150' FWL, Sec. 12, T-26N-N, R-09W-W, NMPM		10.	Field and Pool BALLARD PICTURED CLIFFS
		11.	County and State Co, NM San Juan Co, New Mexico
Subsequent Report Final Abandonment	Plugging Back Non-R Casing Repair Water Altering Casing Conve X Other - Tubing Installati	Shut orsion	off
13.Describe Proposed or Complet			
· · · · · · · · · · · · · · · · · · ·	and clean out to PBTD @ 2061'.		<u>-</u> -
3. Land 1 1/4" tubing at	: 1975`.		3 5
4. RDMO. 5. Return well to product	cion.		
14. I hereby certify that the	e foregoing is true and correct Title Requlatory Administra		ate 11/4/99
(This space for Federal or State	te Office use)		
APPROVED BY CONDITION OF APPROVAL, if any:	Title	Date	ASTRONOM STATE OF THE STATE OF

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Huerfanito Unit #64

Section 12D, T-26-N, R-9-W San Juan County, NM

BALLARD PICTURED CLIFFS WELLBORE SCHEMATIC

CURRENT

ELEVATION: 6197' GL 6207' KB

