



UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Field Office Santa Fe
Lease No. 078000
Unit Huerfano Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	☒ X	WATER REPORT
NOTICE OF INTENTION TO PUMP	☐	WATER REPORT
NOTICE OF INTENTION TO TEST WATER	☐	WATER REPORT
NOTICE OF INTENTION TO REPAIR	☐	WATER REPORT
NOTICE OF INTENTION TO ABANDON	☐	WATER REPORT
NOTICE OF INTENTION TO REPAIR	☐	WATER REPORT
NOTICE OF INTENTION TO ABANDON	☐	WATER REPORT

RECEIVED

U.S. GEOLOGICAL SURVEY
JUN 17 1963

June 14

1963

Well No. 129 is located 1750 ft. from ~~XXX~~ line and 1090 ft. from ~~XXX~~ line of sec. 9

NW/4 Section 9 26-N 9-W N.M.P.M.

Basin Dakota San Juan New Mexico

The elevation of the derrick floor above sea level is 6454 ft.

DETAILS OF WORK

State name of mud and fluid used: ...

It is intended to mud drill a well with rotary tools thru the Dakota formation. Possible producing zones will be perforated and fractured. Est. T.D. 6794'.

Casing Program:

10 3/4" @ 300' with 230 sacks cement circulated to surface.
4 1/2" @ 6794' w/2nd stage collar set @ 6203' or base of Gallup. 3rd stage collar set @ 2323' or 100' below base of Pictured Cliff. Cement 1st stage w/145 sks. cement. 2nd stage w/180 sks. cement. 3rd stage w/185 sks. cement.

The W/2 of Section 9 is dedicated to this well.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company

Address Box 990

Farmington, New Mexico

By

D W Meehan

Title Petroleum Engineer

NEW MEXICO OIL CONSERVATION COMMISSION

Well Location and Acreage Description Plat

Section A.

Date **JUNE 12, 1963**

Operator **EL PASO NATURAL GAS COMPANY** Lease **HUERFANO Unit SF078000**
 Well No. **129** Unit Letter **E** Section **9** Township **26-N** Range **9-W** NMPM
 Located **1750** Feet From **NORTH** Line **1090** Foot From **WEST** Line
 County **SAN JUAN** G. L. Elevation **6444** Section Acreage **320** Acres
 Name of Producing Formation **DAKOTA** Pool **BASIN DAKOTA**


1. Is the Operator the only owner in the dedicated acreage outlined on the plat above?
 Yes ☐ No ☒
2. If the answer to question one is "no", have the interests of all the owners been ascertained by communication, agreement or otherwise? Yes ☒ No ☐ If answer is "yes", Type of consultation:

Unit Well

3. If the answer to question two is "no", list all the owners and their respective interests below:

Owner

Land Description



Section B.

This is to certify that the information in Section A above is true and complete to the best of my knowledge and belief.

El Paso Natural Gas Company


(Operator)

ORIGINAL SIGNED E. S. OBERLY

(Representative)

Box 990

(Address)

Farmington, New Mexico

Scale 4 inches equal 1 mile

This is to certify that the above plat was prepared from field notes of actual surveys made by me or under my supervision and that the same are true and correct to the best of my knowledge and belief.

(Seal)

Date Surveyed **APRIL 1, 1963**

David O. Miller
 Registered Professional Engineer and/or Land Surveyor

Farmington, New Mexico