

COPY FOR
STATE OF NEW MEXICO
OIL CONSERVATION
COMMISSION
SUBMIT IN TRIPLICATE TO
DISTRICT OFFICE

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe

Lease No. 030384

Unit #1 Hickman

AUG 25 1951

OIL CON. COM.

DIST. 5

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

August 20, 1951

Well No. 1 Hickman is located 990 ft. from [N] line and 990 ft. from [W] line of sec. 10

NW 1/4 Sec. 10 (1/4 Sec. and Sec. No.) T-26N (Twp.) R-12W (Range) San Juan (Meridian)
Wildcat (Field) San Juan County (County or Subdivision) New Mexico (State or Territory)

The elevation of the ~~drill floor~~ ground above sea level is 6075 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate muddling jobs, cementing points, and all other important proposed work)

15-20-8 100 ft. cement plug was placed in the bottom of the hole, the hole filled with heavy mud, the pipe was shot off at 753 ft. and pulled. A 30 ft. cement plug was placed in the top of the surface pipe with a steel marker. Lease was cleaned and leveled.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company DON DANVERS

Address 525 Milan Building

San Antonio, Texas

By R. H. Young

Title Agent