1.

SF-078859-A

Western A

#4

Gallegos Gallup

8, 26-N, 11-W

6175GL

San Juan | New Mexico

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:				SUBSEQUENT REPORT OF:			
TEST WATER SHUT-OFF		PULL OR ALTER CASING		WATER SHUT-OFF		REPAIRING WELL	
FRACTURE TREAT		MULTIPLE COMPLETE		FRACTURE TREATMENT		ALTERING CASING	
SHOOT OR ACIDIZE		ABANDON*	X	SHOOTING OR ACIDIZING		ABANDONMENT*	
REPAIR WELL		CHANGE PLANS		(Other)			
(Other)				(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)			

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

(Est. date to start work 4-1-68)

1. Load hole with mud laden fluid.
2. Squeeze Gallup perforations.
3. Shoot pipe loose at free point and pull.
4. Spot 100' cement plug 50' in and 50' out of stub.
5. Spot 100' cement plug across top of picture cliff.
6. Spot 100' cement plug at base of Ojo Alamo.
7. Place cement plug in top of surface with welded marker in place.
8. Clean location.

RECEIVED
MAR 29 1968
U. S. GEOLOGICAL SURVEY
FARMINGTON, N.

RECEIVED
APR 1 1968
OIL CON. COM.
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED Jim Pappe TITLE Agent DATE 3-20-68

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side