

(SUBMIT IN TRIPLICATE)

Indian Agency **Navajo Tribal**

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____
Lease No. **I-149-IND-9108**

X			

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 17, 19 59

Delhi Taylor Pool Unit

Well No. **1-D** is located **790** ft. from **S** line and **790** ft. from **W** line of sec. **3**

SW SW/4 Sec. 3

(1/4 Sec. and Sec. No.)

26N

(Twp.)

11W

(Range)

NMPM

(Meridian)

Undesignated Dakota

(Field)

San Juan

(County or Subdivision)

New Mexico

(State or Territory)

The elevation of the derrick floor above sea level is **6372** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spud Date **February 14, 1959.**

February 14, 1959 Total Depth 195'.

**Ran 6 joints, 10-3/4", 32.75, J-55 Casing (179') set at 192' with
125 sacks regular cement, 3% CaCl₂ circulated to surface
Held 500#/30 Minutes.**



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **El Paso Natural Gas Products Company**

Address **Post Office Box 1565
Farmington, New Mexico**

ORIGINAL SIGNED BY: **JOSEPH E. KREGER**

By _____

Title **Petroleum Engineer**

