



OIL CONSERVATION COMMISSION

STATE OF NEW MEXICO
1000 RIO BRAZOS ROAD - AZTEC
87410

GOVERNOR
BRUCE KING
CHAIRMAN
LAND COMMISSIONER
ALEX J. ARMIJO
MEMBER
STATE GEOLOGIST
A. L. PORTER, JR.
SECRETARY - DIRECTOR

December 1, 1971

Mr. Carl Matthews
El Paso Natural Gas Company
P. O. Box 990
Farmington, New Mexico

Re: El Paso Natural Gas Co.
Huerfano Unit #60
M-4-26N-9W

Dear Mr. Matthews:

The attached copy of the 1971 annual Packer-Leakage Test Report for the subject well indicates communication between the producing zones.

You are hereby directed to take immediate action to cause the zones to be separated as required by Rule 112-A and the order which authorized the dual completion.

If there are questions, please contact us.

Yours very truly,

A. R. Kendrick
A. R. Kendrick
Engineer, District #3

ARK:mc

Attach.


cc w/ attach: Oil Conservation Commission
Santa Fe, New Mexico

NEW MEXICO OIL CONSERVATION COMMISSION NORTHWEST NEW MEXICO PACKER-LEAKAGE TEST

Operator El Paso Natural Gas Company				Well Name and Number Huerfanito Unit No. 60 (GD)			
Unit M. Sec. 4 Twp. 26 Rge. 9				TYPE OF TEST--> 1971	DATE OF TEST 1971		
UPPER COMPLETION	Reservoir or Pool GL	☒ GAS ☐ OIL	☒ FLOWING ☐ ARTIFICIAL LIFT	☐ NEW ☐ OLD	FLOWING TEST ☒ CASING ☐ TUBING		
LOWER COMPLETION	Reservoir or Pool DK	☒ GAS ☐ OIL	☒ FLOWING ☐ ARTIFICIAL LIFT	☐ CASING ☒ TUBING	FLOWING TEST ☐ CASING ☒ TUBING		

Date	Lower Zone		Upper Zone		
	Shut-in		Shut-in	Flow Test	
	Casing	Tubing	Casing	Tubing	Flow Rate
9-20		635	634	X	X
9-21		676	675		
9-22		697	695		
9-23		449	X	410	456
9-23		428		392	415

Remarks:



The results of this test indicate (~~No Packer Leakage~~) (Packer Leakage) in this well.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

operator notified to repair 12-1-71

APPROVED _____, 19____
 NEW MEXICO OIL CONSERVATION COMMISSION

BY _____


OPERATOR EL PASO NATURAL GAS COMPANY

BY R. E. Fielder
 R. E. Fielder

TITLE Well Test Engineer

DATE _____

EPNG
 Annual Packer Leakage Test
 1971
 Huertanito Unit No. 60 (GD)
 Unit M Sec. 4 - T26N-R9W
 San Juan County, New Mexico



○ GL Zone
 ● DK Zone