

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

SF 02901

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

FOSTER

9. WELL NO.

4

10. FIELD AND POOL, OR WILDCAT

Basin Dakota-Blango Mv

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 4, 26-N, 8-W,
N.M.P.M.

12. COUNTY OR PARISH

SAN JUAN

13. STATE

NEW MEXICO

1. OIL ☐ GAS ☒ OTHER
WELL WELL

2. NAME OF OPERATOR

SOUTHERN UNION PRODUCTION COMPANY

3. ADDRESS OF OPERATOR

P. O. Box 808; Farmington, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1850 FEET FROM NORTH LINE AND 2220 FEET FROM EAST LINE.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6469 D.F.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☒
☐
☐
☐

REPAIRING WELL

☐
☐
☐
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. SPUDDER 12-1/4" SURFACE HOLE, OCTOBER 15, 1964. DRILLED TO T.D. OF 305' R.K.B.
2. RAN 10 JTS. 8-5/8", 24#, J-55 CCG. LANDED @ 305 R.K.B. CEMENTED WITH 200 BAGS REGULAR CEMENT CONTAINING 2% CALCIUM CHLORIDE. PLUG DOWN 12:00 P.M. 10/15/64. CEMENT CIRCULATED TO SURFACE.
3. NIPPLED UP AND PRESSURE TESTED SURFACE CASING AND B.O.P. TO 800 PSI FOR 30 MIN. TESTED OK.
4. DRILLED OUT FROM UNDER SURFACE CASING WITH 7-7/8" BIT ON OCTOBER 16, 1964.

REC'D
NOV 4
OIL CO.
DIST.

18. I hereby certify that the foregoing is true and correct

SIGNED

Gilbert D. Roland, Jr.
GILBERT D. ROLAND, JR.

TITLE

DRILLING SUPERINTENDENT

DATE

OCTOBER 29, 1964

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations, on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.