

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____
Lease No. SP 078286
Unit Walker

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

_____ August 20 _____, 19 58

Well No. A-1 is located 1980 ft. from N line and 610 ft. from E line of sec. 4

NE 4 4 20 12 SPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)


(Field) San Juan New Mexico
(County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6115 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

8-20-58 Perforated 5114-5144', w/2 jets & 2 bullets per ft.
sand fraced w/40,000 gal. lease oil, 50,000-20-40
sand and 110 rubber balls.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Petro-Atlas, Inc.

Address 729 East Main

Farmington, New Mexico

By R. E. Cove

Title Engineer