



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 077930
Unit Huerfano Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....	<u>water Fracture</u>	<u>X</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 17, 19 55

Well No. 49 is located 1650 ft. from (N) line and 990 ft. from (E) line of sec. 5

NE Section 5
(¼ Sec. and Sec. No.)

26N
(Twp.)

9W
(Range)

RMPM
(Meridian)

Wildcat
(Field)

San Juan
(County or Subdivision)

New Mexico
(State or Territory)

The elevation of the derrick floor above sea level is 6501 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

2-16-56 Total Depth 2310'.

water fractured Pictured Cliff, interval 2247-2310 with 40,000 gallons water and 60,000 sand. Breakdown pressure 0#, maximum pressure 100#, average treating pressure 900#, Injection rate 62 bbls./min. Flush 5000 gallons. Natural gage 139 MCF/D.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company E. Paso Natural Gas Company

Address Box 997

Farmington, New Mexico

By

Petroleum Engineer

Title

