

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office

Lease No. **SF 078286B**

Unit **Walker "B"**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	X
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 4, 1959

Well No. **1** is located **1650** ft. from **N** line and **2310** ft. from **E** line of sec. **4**
NW **4** **26N** **12W** **NM**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Gallegos Gallup **San Juan** **New Mexico**
(Field) (County or Subdivision) (State or Territory)


The elevation of the derrick floor above sea level is **5986** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

3-3-59 Spudded

3-3-59 Set 8 5/8" - 24# J-55 SS casing at 167' w/ 85 sacks cement containing 2% calcium chloride.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Petro-atlas, Inc.**

Address **729 E. Main St.**

Farmington, N.M.

By **N.B. Gove**
Title **Engineer**