

(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY


Land Office San Juan  
Lease No. 52221  
Unit American Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		water pressure	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 07 is located 800 ft. from N line and 1000 ft. from W line of sec. 6  
24 (Twp.) 12 (Range) 10N (Meridian)  
San Juan (County or Subdivision) New Mexico (State or Territory)



The elevation of the derrick floor above sea level is 5500 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

7-29-56 Total Depth 2200'. Cement Depth 2100'.  
Water fractured Pictured Cliffs perforated intervals 2177-2184, 2127-2132  
with 52,500 gallons water and 4,600 sand. Breakdown pressure 1500',  
maximum pressure 1500', average treating pressure 1300'. Injection rate  
63.4 gals./min. Flush 2100 gallons. Natural gas none.

ILLEGIBLE

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company

Address Box 777  
Armadillo, New Mexico

By [Signature]  
Title Retired Engineer