5. LEASE

UNITED STATES

DEPARTMENT OF THE INTERIOR	NM 12760
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME
1. oil gas other Dry Hole 2. NAME OF OPERATOR J. Gregroy Merrion & Robert L. Bayless	Liberty Bell 9. WELL NO. 1 10. FIELD OR WILDCAT NAME.
3. ADDRESS OF OPERATOR P.O. BOX 507, Farmington, NM 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 790 FNL & 1850 FWL AT TOP PROD. INTERVAL: AT TOTAL DEPTH: same	Wildcat 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 5, T26N, Rl2W 12. COUNTY OR PARISH 13. STATE San JUan New Mexico
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING SHOULTIPLE COMPLÉTE SHANGE ZONES ABANDON* (other) Surface Rehabilitation	9 (1091) Report results of multiple completion or zone change of Form 9-330.) GICAL SURVEY TON, N. M.
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is directly measured and true vertical depths for all markers and zones pertinent of the control of the	to this work.)*

01-15-80 Removed large concrete block. Unable to schedule seeding until summer of 1980.

OILSEON. COM. Subsurface Safety Valve: Manu. and Type ___ 18. I hereby pertify that the foregoing is true and correct Engineer Februar TITLE . DATE _ (This space for Federal or State office use) APPROVED BY _ TITLE .

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

FEB 22 1980