



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office New Mexico ✓
Lease No. 012202
Unit Black

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

SEP 24 1959

SURVEY
ACTIVITY

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 22, 1959

Well No. 4-2 is located 850 ft. from S line and 1650 ft. from W line of sec. 12

12 Sec. 12 (1/4 Sec. and Sec. No.) T7N (Twp.) 3W (Range) N.M.P.M. (Meridian)
Black (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6675 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

On 8-24-59 Total Depth 5490'.
Run 36 joints of 1 1/2" O.D., 13.5# Liner (135') from 3151' to 5490' with 100 sacks regular cement, 100 sacks Formix, 1 1/4" Floccin/sk., 6% Gel, 1/2" Fine stuffplug/sk. followed with 50 sacks Best cement.

Run 1000' / 30 minutes.

top of cement by temperature survey at 3151'.

RECEIVED
SEP 25 1959
OIL CON. COM.
DIST. 3

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company

Address Box 997

Farmington, New Mexico

By Original Signed By: D.H. Oheim

Title Petroleum Engineer