


Land Office Santa Fe
Lease No. NM 05791
Unit _____

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY



SUNDRY NOTICES AND REPORTS ON **WELLS** RECEIVED

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-PAIRING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....	<u>Subsequent Report of Surface Pipe</u>	<u>X</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 2, 1958

Well No. 3 is located 1090 ft. from SE line and 1550 ft. from E line of sec. 10

SE 1/4 10 (1/4 Sec. and Sec. No.) 27-N (Twp.) 8-W (Range) NMPM (Meridian)
So. Blanco Pictured Cliffs (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is _____ ft. 5912' G.L.

DETAILS OF WORK

(State names of and expected depths to objective sands; show size, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Spudded well w/surface spudder on September 18, 1958.
Set 87.65' of 8 5/8" O.D. 25.65# Grade "B" Suls casing in 12 1/4" hole at 97'.
Cemented pipe w/70 sx neat cement on September 19, 1958. Cement circulated to surface. Tested pipe on October 2, 1958 w/800# for 30 min. Held O.K.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company WESTERN NATURAL GAS COMPANY

Address 211 1/2 W. Main

Farmington, New Mexico

By Calvin M. Rayner
Title Petroleum Engineer