Form 9-881 a (Feb. 1951)

ō	 	
ļ	 	

## (SUBMIT IN TRIPLICATE)

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	Santa Pe
Lease No	078481-4
Unit	******

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTER	NTION TO DRILL	SUBSEQUENT	REPORT OF WATER SHUT-O	(F		
NOTICE OF INTER	NTION TO CHANGE PLANS	SUBSEQUENT	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING			
NOTICE OF INTER	NTION TO TEST WATER SHUT-OFF	SUBSEQUENT	SUBSEQUENT REPORT OF ALTERING CASING.			
NOTICE OF INTER	NTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR			
NOTICE OF INTER	NTION TO SHOOT OR ACIDIZE	SUBSEQUENT	SUBSEQUENT REPORT OF ABANDONMENTSUPPLEMENTARY WELL HISTORY			
NOTICE OF INTER	NTION TO PULL OR ALIER CASING	SUPPLEMENTA				
NOTICE OF INTER	NTION TO ABANDON WELL					
	(INDICATE ABOVE BY CHECK M	ARK NATURE OF REPORT	, NOTICE, OR OTHER DATA)		!	
			Ju	ly 17.	10 🕏	
n k	g #36	***************************************		,		
Well No.	Panson is located 1000 ft. fr	om $\left\{ egin{array}{c} \mathbf{N} \end{array} \right\}$ line and	$\frac{560}{\text{tt. from}}$	$\binom{k}{l}$ line of sec	10	
Mi AL. Set	c. 10 T 27 B	r R <b>O</b> e	M M P M	J		
(1/2 Sec. an	d Sec. No.) (Twp.)	(Range)	(Meridian)	p.		
(Fie	eld) (Cou	nty or Subdivision)	(State o	r Territory)		
Casing	d expected depths to objective sands; showing points, and					
3-5/3°	surface casing - 1	or, with 10	O sacks come:	at		
5-1 <i>E</i> "	production casing .	. 2185', wit	th 200 sacks	oement		
					)	
					<u>}</u>	
					-	
					$\mathbb{C}^{\mathbb{N}^{N}}$ .	
					1	
	hat this plan of work must receive approve		logical Survey before operat	ions may be comman	ced.	
Company	& 3 Drilling Co.,	inc.				
	50 Best 57th St.					
71001000	or York 19. H.Y.		. S Cale	Sale de tra 🗣 🕫		

Title office ner.