


(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Santa Fe  
Lease No. 11-002-1  
Unit San Juan 2-7 Unit  
11-0-01-47



## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 11-002-1 is located 100 ft. from N line and 100 ft. from E line of sec. 1  
1 (1/4 Sec. and Sec. No.) 1 (Twp.) 1 (Range) 1 (Meridian)  
1 (Field) 1 (County or Subdivision) 1 (State or Territory)


The elevation of the derrick floor above sea level is 1000 ft.

### DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total depth 100 ft.  
The 10 points 1 1/2, 15-50, 3-75 liner (2300') set from 100 to 100 ft. with 100 sacks regular cement, 100 sacks regular cement, 50 gal. 2 1/2 lb. Fluorocarbon. Followed by 10 sacks regular cement.  
Hold 1000 for 30 minutes.

To be cement by temperature survey at 1000.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company San Juan 2-7 Unit  
Address San Juan, N.M.  
By Original Signed D. C. Johnston  
Title Geological Survey



\_\_\_\_\_

\_\_\_\_\_