

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 070972-A
Unit San Juan 20-7
14-00-001-459

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 19, 19 57


Well No. 01 is located 1672 ft. from N line and 1750 ft. from E line of sec. 2
NE Sec. 9 (1/4 Sec. and Sec. No.) 21N 7W N.M.P.M.
(Twp.) (Range) (Meridian)
So. Blanco P.C. Ext. & Rio Arriba New Mexico
Blanco M. V. (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 6057 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudlogging jobs, cementing points, and all other important proposed work)

10-20-57 Total depth 5843'.
Ran 57 joints 5 1/2", 19.50#, J-55 liner (2319') set from 3519 to 5830' with
150 sacks regular cement, 150 sacks lozmix, 6 1/2 Gal.
Held 1000# for 30 minutes.
Top of cement by temperature survey at 3519'.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company El Paso Natural Gas Company
Address Box 991
Farmington, New Mexico
By Original Signed D. C. Johnston
Title Petroleum Engineer

