

4-USGS

1-WD

1-D

1-F

(SUBMIT IN TRIPLICATE)

Budget Bureau No. 42-R358.4.
Approval expires 12-31-60.

		X

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office

Lease No. **SF-078899**

Unit

Henderson Federal

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)


6/14, 1961

Well No. 1 is located 790 ft. from N line and 790 ft. from E line of sec. 5NE 1/4 NE 1/4 Sec. 5
(1/4 Sec. and Sec. No.)26N
(Twp.)11W
(Range)NMPM
(Meridian)Basin Dakota
(Field)San Juan
(County or Subdivision)New Mexico
(State or Territory)The elevation of the derrick floor above sea level is 6234 ft. G.L.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

6/12/61 - Spudded @ 5:30 PM in 13 3/4" surface hole. Drld. to 220', ran & set 209.91' of 10 3/4" 32.50# casing @ 198' KB w/150 sx 2% HA-5, plug down @ 1:00 AM. 6/13/61 cement circulated. WOC 11 1/2 hrs. test casing w/750# for 30 minutes held OK. Began drilling @ 12:30 PM 6/13/61.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Southwest Production CompanyAddress 162 Petr. Center Bldg.,
Farmington, New MexicoBy Original signed by
Carl W. SmithTitle Production Superintendent