

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. 070970
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 1 is located 890 ft. from N line and 890 ft. from W line of sec. 27
SW/4 Section 27 T13N R13E W13N
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Unidentified District San Juan New Mexico
 (Field) (County or Subdivision) (State or Territory)


The elevation of the ground level above sea level is 699 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

We wish to report the running and cementing of surface casing.

1. Drilled 12 1/4" hole to 324'.
2. Run 307' 8 5/8" OD 28#, 2-40 casing and set at 317' with float collar.
3. Cemented with 175 ex Portland cement and 36 Galig. Plug down 10/23/59.
4. WCT 24 hrs. Tested at 600 psi for 30 minutes. Held OK.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Tennessee Gas Transmission Company

Address P. O. Box 1714

Durango, Colorado

By R. H. Walker R. H. Walker

Title District Production Superintendent