

(SUBMIT IN TRIPLICATE)

Indian Agency Navajo

14-90-603-512

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____

Oil Lease No. 67,579

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL _____	SUBSEQUENT REPORT OF WATER SHUT-OFF _____
NOTICE OF INTENTION TO CHANGE PLANS _____	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING _____
NOTICE OF INTENTION TO TEST WATER SHUT-OFF _____	SUBSEQUENT REPORT OF ALTERING CASING _____
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL _____	SUBSEQUENT REPORT OF REDRILLING OR REPAIR _____
NOTICE OF INTENTION TO SHOOT OR ACIDIZE _____	SUBSEQUENT REPORT OF ABANDONMENT _____
NOTICE OF INTENTION TO PULL OR ALTER CASING _____	SUPPLEMENTARY WELL HISTORY _____
NOTICE OF INTENTION TO ABANDON WELL _____	<u>Subsequent Report of 677</u>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

NAVAJO TRIBE OF INDIANS

Farmington, N. M. January 2, 1957

Well No. 1 is located 790 ft. from N line and 790 ft. from E line of sec. 30

NE/4 Sec. 30

T-26-N

R-19-W

(1/4 Sec. and Sec. No.)

(Twp.)

(Range)

(Meridian)

Beautiful Mountain 4/8

San Juan

New Mexico

(Field)

(County or Subdivision)

(State or Territory)

The elevation of the derrick floor above sea level is 6470 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

12/23/56: DRY #3 6450 to 6673 w/Johnson tool, 1" TG & 3/4" BG. TO 30 min. Opened w/very weak blow for 6 min. & died. IN & PR 3400. MIN. & MAX. 77 OF. SUP OF after 30 min. Recovered 7' drilling mud. No shows. Test satisfactory.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Humble Oil & Refining Company

Address Box 1268

Farmington, New Mexico

COPY ORIGINAL
By Russell M. Lilly
Dist. Dept.

Title _____

