UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Form 9–331 Dec. 1973	Form Approved. Budget Bureau No. 42–R1424				
UNITED STATES	5. LEASE				
DEPARTMENT OF THE INTERIOR	SF_078001-B				
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME				
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)	7. UNIT AGREEMENT NAME Huerfano Unit 8. FARM OR LEASE NAME				
1. oil gas X other	Huerfano Unit 9. WELL NO.				
2. NAME OF OPERATOR	#132				
El Paso Natural Gas Company	10. FIELD OR WILDCAT NAME				
3. ADDRESS OF OPERATOR	Basin Dakota				
P.O. Box 4289, Farmington, New Mexico 87499 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 890'S, 890'E, Sec. 26, T26N, R10W AT TOP PROD. INTERVAL: AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL CR ALTER CASING MULTIPLE COMPLETE	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 26, T-26-N, R-10-W 12. COUNTY OR PARISH San Juan New Mexico 14. API NO. 15. ELEVATIONS (SHOW DF, KDB, AND WD) 6711' GL (NOTE: Report results of multiple completion or zone change on Form 9-330.)				
CHANGE ZONES	90. 3 . 3 . 3 . 3 . 3 . 3 . 3 . 3 . 3 . 3				

8-25-83: Set a cement retainer at 6514' to check for a possible casing leak.

					i Sa	: 1
Subsurface Safety Valve: Manu. and Type		Set @) Ft.			
18. I hereby certify that the foregoing is tru	ie and correct	Production Engineer	DATE	August 29,	1983	· · · · · · · · · · · · · · · · · · ·
	(This space for	Federal or State office use)		ACCEPTED FO	R RECO)RD
APPROVED BYCONDITIONS OF APPROVAL, IF ANY:	TITLE			E		· · · · ·
				SEP 07	1983	

FARMING OUR STOUNGE AREA

P. P. C. Carlon