

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

MM-029144

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

PUBCO PETROLEUM CORPORATION

3. ADDRESS OF OPERATOR

P.O. Box P, Artec, New Mexico

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface **990' FWL & 330' FWL, Sec. 9, T.27N., R.8W.**

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

FEDERAL

9. WELL NO.

16

10. FIELD AND POOL, OR WILDCAT

Basin Dakota

11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA

Unit M, 9-27N-8W.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6709' Gr. 6721' KB.

12. COUNTY OR PARISH

San Juan

13. STATE

N.Mex.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐

PULL OR ALTER CASING

☐

FRACTURE TREAT

☐

MULTIPLE COMPLETE

☐

SHOOT OR ACIDIZE

☐

ABANDON*

☐

REPAIR WELL

☐

CHANGE PLANS

☐

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☒

REPAIRING WELL

☐

FRACTURE TREATMENT

☐

ALTERING CASING

☐

SHOOTING OR ACIDIZING

☐

ABANDONMENT*

☐

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

6-17-67:

Drilled 12 1/4" hole to 2797' KB.

Ran 97 joints 8 5/8" OD, 24.0#, J-55 casing, landed at 2795' KB.

Cemented with 275 sack HYS-C 400, followed by 100 sack Class C, 2# CaCl.

Plug down at 9:08 A.M., 6-17-67, with 1400 psi.

Tested casing to 1000 psi. Held OK.



RECEIVED

JUN 22 1967

U. S. GEOLOGICAL SURVEY
WASHINGTON, D. C.

18. I hereby certify that the foregoing is true and correct

SIGNED

Stanley C. Walker

TITLE **Petroleum Engineer**

DATE **6-19-67**

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: