UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells	
1. Type of Well GAS	5. Lease Number SF-078571 6. If Indian, All. or Tribe Name
2. Name of Operator	7. Unit Agreement Name
MERIDIAN OIL OIL CON DIST	8. Well Name & Number
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 87499 (505) 326-9700	Day B #4 9. API Well No.
4. Location of Well, Footage, Sec., T, R, M 1700'FSL, 1616'FWL, Section 7, T-27-N, R-8-W, NMPM	10. Field and Pool Basin Dakota 11. County and State San Juan
12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE Type of Submission Type of Ac	tion
Recompletion	_ Change of Plans _ New Construction Non-Routine Fracturing
X_ Casing Repair X_ Casing Repair Altering Casing Other -	Non-Routine Fracturing Water Shut off Conversion to Injection
13. Describe Proposed or Completed Operations	
The following casing leak repair work was done by TOOH w/2 3/8" tbg. Located csg leak 5174-4848'. I 574-636'. Squeezed lower leak w/150 sx cw/150 sx cmt. Drl out upper leak and PT leak and PT 500#/15 min, ok. Drl out cmt production tbg @ 735' w/Baker Model "R"	cocated upper csg leak cmt. Squeeze upper leak 500#, ok. Drl out lower cret @ 7191'. Land
9/22/93 <u>e</u> 201: Fed 2000 109	070 FARALISION, N
Signed Man Shadhuld Title Regulatory As	Correct. Ffairs Date 8/26/93 ACCEPTED FOR RECORD
	ACCEPTED FOR RECORD
(This space for Federal or State Office use) APPROVED BY	SEP16 1993
CONDITION OF STEROVAL, IT dily.	FARMINGTON DISTRICT OFFICE