UNITED STATES

DEPARTMENT OF THE INTERIOR

	es and Reports on Wells		
. Type of Well	997.89 13 PN 4		Lease Number SF-078000-A If Indian, All. or Tribe Name
GAD			TIIDE Name
		V 屋M·	Unit Agreement Name
. Name of Operator BURLINGTON RESOURCES OIL &	GAS COMPANY	1999 世	Huerfano Unit
. Address & Phone No. of Operato PO Box 4289, Farmington, NM . Location of Well, Footage, Sec	87499 (505) 326-9700 DISTO	9.	30-045-20395 Field and Pool
1790'FSL 1650'FEL, Sec.29, T-2	6-N, R-9-W, NMPM	11.	Basin Dakota County and State San Juan Co, NM
X Subsequent Report Final Abandonment 3. Describe Proposed or Comple	Plugging Back Non Casing Repair Wat Altering Casing Con X Other - tubing repair	er Shut of	Fracturing Ef
	DP. TIH, tag up @ 6759'. TOC /8" 4.7# J-55 tbg, set @ 668		

BY Som