

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LM 05791

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Graham "B" #1 Federal

9. WELL NO.

7

10. FIELD AND POOL, OR WILDCAT

So. Blanco-Pictured Cliffs

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Section 1-27E-8W

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

1. Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. NAME OF OPERATOR

Atlantic Richfield Co., Successor By Merger To Sinclair Oil Corp.

3. ADDRESS OF OPERATOR

501 Lincoln Tower Bldg., 1600 Lincoln St., Denver, Colo. 80203

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also Sec. 17 below.)

Unit letter "F" - 1840' f/North & 1740' f/West lines of Sec. 1

14. PERMIT NO.

ELEVATIONS (Show whether DF, RT, CR, etc.)

Mr. J. T. McGrath, 2/17/69 5350' T.L.

15. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	STOP OR ALTER CASING
FRAC TURE TREAT	COMPLETE COMPLETE
SHOOT OR ACIDIZE	SHOOT OR ACIDIZE*
REPAIR WELL	CHANGE PLANS
(Other)	

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	REPAIRING WELL
FRAC TURE TREATMENT	ALTERING CASING
SHOOTING OR ACIDIZING	ABANDONMENT*
(Other) Completion	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

16. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

ITTC - 2643'

- 3/24-26/69: Lipped up. Perforated Pictured Cliffs formation f/2561'-70' & 2571'-90' w/ 2 holes per foot.
- 3/27-4/1/69: Shut down because of mud, & hauling free water.
- 4/2/69: Broke Pictured Cliffs perforations 2564-70' & 2571-90' w/3000#. Freed w/ 36,000 gals gelled water w/2 1/2 WK-2 per 1000 gals & 34,000 10-20 sand. Average treating pressure 2300#, AIR 41.2 BPM. Temp. shut down 800#, to 700# in 10 mins.
- 4/3-4/7/69: Went on completion unit.
- 4/8/69: MI & RU compl unit.
- 4/9/69: Ran tubing, cleaned out sand to 2601'. Set 83 jts 2-3/8" GR tubing @ 2571'. Swabbed well 3 hrs., well kicked off.
- 4/10/69: Well flowed 19 hrs., BRO 2190 MCFD f/Pictured Cliffs perforations 2564-70' & 2571-90' through 2" open tubing, FCP 250#. ST 1 PM 4-10-69. COMPLETED GAS WELL 4-10-69. Waiting on pipeline connection.

18. I hereby certify that the foregoing is true and correct

SIGNED

M. E. Brown

TITLE

Chief Office Clerk

DATE

4/11/69

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY

RECEIVED

APR 13 1969

*See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY
FARMER BUILDING