



Odessa Natural Corporation
BURROUGHS STATE NO. 1
Section 36, T-26N, R-11W
San Juan County, New Mexico

WEEKLY DRILLING REPORT:

11-23-71:
W.O.C.

11-24-71:
W.O.C.

11-25-71:
GIH w/bit to drill out.

11-26-71:
GIH w/3-7/8" bit. Three 3-1/8" drill collars. Drld stage collar 1787 and 4393'.
Ran bit to float @ 6314'. Shut down @ 6:00 p.m. 11-25-71. This a.m., spotted
acid, prep to perf and treat.

11-27-71:
Perf: 6168 - 6180 (45')
6196 - 6206 (9')
6240 - 6246 (13')

Treated w/5030 gals of 3% CaCl wtr as preflush, 43,960 gals of 3% CaCl wtr,
40,000# 20/40 sand. Flushed w/5030 gals of 3% CaCl wtr. Used 30 ball sealers.
Avg injection rate 3300# @ 47-1/2 BPM. ISI 1400#, 15 min/800#.

11-28-71:
Well on vacuum. Ran tbg to 6232'. Swbd from 11:30 am to 2:15 pm. Well kicked
off. Flwg at rate of 4.8 MMCF w/mist of wtr & hvy mist of condensate. FTP
175#, flwd to 5:30 pm 11-27-71. SI. SITP @ 7:30 am 1250# 11-28-71. Rigging
down unit.

11-29-71:
Shut-in. Will flow to clean up and test.

