

S

Jan. 6, 1976

30-015-21522

F. Loc. 1110/N; 1470/E Elev. 6147 GL Spd. _____ Comp. _____ TD _____ PB _____Casing S. _____ @ _____ W _____ Sx. Int. _____ @ _____ W _____ Sx. Pr. _____ @ _____ W _____ Sx. T. _____ @ _____
Csg. Perf. _____ Prod. Stim. _____T
R
A
N
S

I.P. _____ BO/D _____ MCF/D After _____ Hrs. SICP _____ PSI After _____ Days GOR _____ Grav. _____ 1st Del. _____ s _____

TOPS		NITD	Well Log	TEST DATA							Ref. No.
Kirtland		C-103	Plat	Schd.	PC	Q	PW	PD	D		
Fruitland		C-104	Electric Log								
Pictured Cliffs			C-122								
Cliff House		Ditr	Dfa								
Menefee		Datr	Dac								
Point Lookout		Abandoned Location ABANDONED LOCATION 162									
Mancos											
Gallup											
Sanostee											
Greenhorn											
Dakota											
Morrison											
Entrada											

P
O

15011andoPC Co. SJ S 2 T 250 R CW UB Oper. EPNG Co.

Lse. Durrant/ie

No. 11