(Nov. 1002)		1 - 1 - 1 - 1 - 2 + 1 + 1 + 1 + 1 + 1 + 1 + 1 + 1 + 1 +		(Other Instance	diana an an I	Budget Burea	u No. 42-RI
(May 1963)	DEPARTM	IENT OF THE	INTERIOF	(Other instructions verse side)	tions on re-	5. LEASE DESIGNATION	
		EOLOGICAL SU				NM 0557296	71
* 0.15.15.1				LAMELLO		6. IF INDIAN, ALLOTTEE	OR TRIBE NAME
SUND	RY NOTE	CES AND REP	ORIS ON	WELLS			
(Do not use this for U	m for proposa Jse "APPLICA"	ls to drill or to deeperion FOR PERMIT—"	for such propos	sais.)	ervoir.	•	
<u>. </u>						7. UNIT AGREEMENT NA	ME
OIL GAS X	OTHER				l		
NAME OF OPERATOR						8. FARM OR LEASE NAM	E
Dugan Production Corp.						Hard Deal	
3. ADDRESS OF OPERATOR						9. WELL NO.	
Box 234, Farmington, NM 87401						1	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*						10. FIELD AND POOL, OR WILDCAT	
See also space 17 below.) At surface						Wildcat	
1190' FSL - 890' FEL						11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA	
· ·					į	SULVEI OR MANA	
						Sec. 18, T2	6N, Rl2W
14. PERMIT NO.		15. ELEVATIONS (Show	whether pr, RT,	GR, etc.)		12. COUNTY OR PARISH	13. STATE
			6023' GR			San Juan	NM
	<i>C</i> : 1 A	т .	مالا عدمال	(NI/ : D		har Data	
16.	Check Ap	propriate Box To I	naicate Nati	ire of Notice, n	tepon, or Or	ner Data	<u>.</u>
NO:	CICE OF INTENT	non ro:	1	- 20	SUBSEQUE	NT REPORT OF:	
TEST WATER SHUT-OFF	P	ULL OR ALTER CASING		WATER SHUT-O	fø 🗌	REPAIRING V	VELL
FRACTURE TREAM	 ·	ULTIPLE COMPLETE		FRACTURE TREA	TMENT	ALTERING CA	ASING
SHOOT OR ACIDIZE		BANDON*		SHOOTING OR A	CIDIZING	ABANDONMEX	Y X
REPAIR WELL	c	HANGE PLANS		(Other)			
(Other)				(Note: F Completio	leport results of on or Recomplet	f multiple completion of ion Report and Log for	on Well m.)
17. DESCRIBE PROPOSED OR C	OMPLETED OPER	ATIONS (Clearly state	all pertinent de	tails and give be	rtinent detes 1	cluding estimated data	e of starting any
proposed work. If we nent to this work.) *	rell is direction	nally drilled, give subs	uriace locations	and measured an	d true verticui	depths for all markers	and somes perci-
							<u>.</u>
	1.77						
THIS WELL WA	S PLUGGE	AND ABANDONI	ED IN THE	FOLLOWING	MANNER 7-	3-75:	3
l. Spo	tted 25	sx cement plug	g 1200-10	00".			<i>√</i> (3 / −
							12. W.
2. Spo	tted 13	sx cement plug	200-100	1		162	Co.
						July 1	3 / B
3. Spc	tted 2 s	k cement plug	in surfa	ce pipe		1 20 6	PA /
_						100	of 3
4. Ere	cted dry	hole marker,	cleaned	up location	, and aba	ndoned we	
-•	•	·					
				i			
				1	A Marin Was		
				1	JUL	s 1975	;
,		•		1	JUL	0 10 - 12	
				*		h i	
				1	U. S. GEOLOG	HON, N. M.	
				1	FARMING	IO(II)	
	, ^						
18. I hereby certify that the	ae foregoing is	true and correct					
SIGNED	4. KUL	Chilin T	ITLE	Engineer		DATE 7-7-	·75
	is A. Dug	an .					
(This space for Federa	l or State offic	(re (use)					
אם משמטמממא		T	ITLE			DATE	<u></u>
APPROVED BY	ROVAL, IF A			-			