

MERRION & BAYLESS

CHACO #2

Section 7, T26N, R12W
San Juan County, New Mexico

SLOPE TESTS

Depth

Hole Deviation

600 ft.
1260 ft.

1/2°
1/2°

State of New Mexico)
) ss
County of San Juan)

I, STEVEN S. DUNN, being first duly sworn, depose and state that the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.

Subscribed and sworn before me this 6th day of April, 1977.

My Commission Expires 9/20/80

Eileen Hare
Notary Public