

MERRION & BAYLESS

CHACO #3

Section 12, T26N, R13W
San Juan County, New Mexico

SLOPE TESTS


Depth

Hole Deviation

525 ft.
1300 ft.

1/8°
1/4°

State of New Mexico)
County of San Juan) ss



I, STEVEN S. DUNN, being first duly sworn, depose and state that the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.

Steven S. Dunn

Subscribed and sworn before me this 6th day of April, 1977.

Steven S. Dunn
Notary Public

My Commission Expires 9/20/80