4-USGS (Farmington) 1-McHugh 1-File Form 9-331 Dec. 1973 UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	Form Approved Budget Bureau No. 42-R1424 5. LEASE NM 12028 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.) 1. oil gas well other 2. NAME OF OPERATOR Jerome P. McHugh 3. ADDRESS OF OPERATOR BOX 234, Farmington, NM 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 1740' FNL - 800' FEL AT TOP PROD. INTERVAL: AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME Chaco Plant 9. WELL NO. #3R 10. FIELD OR WILDCAT NAME COALO FR Pictured Cliffs 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 20 T26N R12W 12. COUNTY OR PARISH 13. STATE San Juan NM 14. API NO. 15. ELEVATIONS (SHOW DF, KDB, AND WD) 6030' GR
TEST WATER SHUT-OFF	lirectionally drilled, give subsurface locations and
Plugged and abandoned well as follows: May 25, 1979 1. Spotted cement plug from 1125 - 1020 2. Spotted surface plug from surface to 3. Cut csg 4' below ground level. June 13, 1979 4. Cleaned up location.	

Subsurface Safety Valve: Manu, and Type ___ Set @ __ __ Ft A. Dugan TITLE Agent DATE 7-30-79 (This space for Federal or State office use)

APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

nunda

Approved as to plugging of the well bore. ructions on Reverse Side Liability under bond is retained until surface restoration is completed.

Tage instructions on Reverse Side

APPROVED AS AMENDED DEC 171984. M. MILLENBACH M. MILLENBACH MANAGER M. MILLENBACH
MANAGER

AREA MANAGER