MERRION & BAYLESS

Chaco #4

Section 7, T26N, R12W San Juan County, New Mexico

SLOPE TESTS

<u>DEPTH</u>	HOLE DEVIATION
450 ft.	1/8°
1020 ft.	1/4°

		1		1 1	
State of New Mexico)	<u>.</u>	,		
County of San Juan) ss)	3			
	,				

I, Steven S. Dunn, being first duly sworn, depose and state that the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.

Subscribed and sworn before me this 21st day of April, 1978

Notary Public

My Commission Expires 9/20/80.