## MERRION & BAYLESS

## CHACO #5

Section 1, T26N, R13W San Juan County, New Mexico

## SLOPE TESTS

DEPTH	HOLE DEVIATION
420 ft.	1/4° 1/4°
1100 ft.	1/4

State of New Mexico ) ) ss
County of San Juan )
I, Steven S. Dunn, being first duly sworn, depose and state that the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.
Subscribed and sworn before me this 21st day of April, 1978.

My Commission Expires 9/20/80.