

MERRION & BAYLESS

■

Chaco #7
Section 1, T26N, R13W
San Juan County, New Mexico

SLOPE TEST

Depth


520 ft.
1320 ft.

Hole Deviation

1/8°
1/4°

State of New Mexico)
) ss
County of San Juan)

I, Steven S. Dunn, being first duly sworn, depose and state that the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.



Subscribed and sworn before me this 6th day of November, 1978.


NOTARY PUBLIC

My Commission Expires 9-20-80

