

6 BLM 1 File
UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☐ OTHER **P & A**

2. NAME OF OPERATOR
DUGAN PRODUCTION CORP.

3. ADDRESS OF OPERATOR
P O Box 208, Farmington, NM 87499

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
1650' FSL - 990' FEL

RECEIVED

SEP 25 1985

**BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA**

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6020' GL

5. LEASE DESIGNATION AND SERIAL NO.

NM 10757

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Irish

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

NIPP-Pictured Cliffs

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 12, T26N, R13W, NMPM

12. COUNTY OR PARISH

San Juan

13. STATE

NM

16. **Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data**

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

This well was plugged and abandoned as follows:

- 1) Filled 2-7/8" OD, 6.5#, C-45 10V tubing for casing from P.B.T.D. of 1270' to surface using 36 sx of cement and displacing with 1/4 bbl water.
- 2) Filled surface casing annulus to surface as per verbal approval from BLM engineer, Steve Mason.
- 3) Installed permanent dry hole marker.
- 4) Filled all pits.
- 5) Cleaned well location of all equipment, pipe, junk and trash.
- 6) Restored surface as directed by the surface management agency.
- 7) Cut off tie-downs.

Approved as to plugging of the well bore.
Liability under bond is retained until
surface restoration is completed.

18. I hereby certify that the foregoing is true and correct

SIGNED

Sherman E. Dugan
Sherman E. Dugan

TITLE

Geologist

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

DATE **9-20-85**

SEP 27 1985

DATE

John F. Hill
John F. Hill

*See Instructions on Reverse Side

NMOCC