## UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Form 9–33.i Dec. 1973	Form Approved. Budget Bureau No. 42–R1424		
UNITED STATES	5. LEASE SF-080238-A 6. IF INDIAN, ALLOTTEE OR TRIBE NAME 7. UNIT AGREEMENT NAME		
DEPARTMENT OF THE INTERIOR			
GEOLOGICAL SURVEY			
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)			
1. oil gas well other dry hole			
2. NAME OF OPERATOR			
J. Gregory Merrion & Robert L. Bayless  3. ADDRESS OF OPERATOR			
P.O. Box 1541, Farmington, NM 87401  4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 1800' FNL & 910' FWL AT TOP PROD. INTERVAL: same	11. SEC., T., R., M., OR BLK. AND SURVEY OR  AREA Sec. 6, T26N, R12W  12. COUNTY OR PARISH San Juan  NM		
AT TOTAL DEPTH:  Same  16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	14. API NO.  15. ELEVATIONS (SHOW DF, KDB, AND WD) 5957 GL		
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:  TEST WATER SHUT-OFF  FRACTURE TREAT  SHOOT OR ACIDIZE  SUBSEQUENT REPORT OF:  SUBSEQUENT REPORT OF:			
REPAIR WELL PULL OR ALTER CASING	(NOTE: Report results of multiple completion or zone completion completion or zone completion complet		
Location X			
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stat including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner	irectionally drilled, give subsurface locations and		
7-25-81 Cut off agains 21 holou CI and	had larabine		

Cut off casing 3' below GL and smoothed location. 7-25-81

Ready for final inspection of location.



Subsurface Safety Valve: Manu. and Type				DIST. 3
18. I hereby certify that the foregoing is true		Engineer	DATE	August 31, 1981
(1	his space for F	Federal or State office	use)	
APPROVED BY	TITLE	<del></del>	DATE _	AGGEPTED FOR RECORD

NMOCC

UH 29 1982