

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

SF 080238A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Chaco

9. WELL NO.

8

10. FIELD AND POOL, OR WILDCAT

NIIP Picture Cliff

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 6, T26N, R12W

12. COUNTY OR PARISH

San Juan

13. STATE

N.M.

1.

OIL ☐ GAS ☒ OTHER

2. NAME OF OPERATOR

J. Gregory Merrion and Robert L. Bayless

3. ADDRESS OF OPERATOR

P.O. Box 1541, Farmington, NM 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)
At surface

790 FSL and 1850 FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5970 ft. G.L.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☒

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Intend to abandon by filling 2-7/8" production string, to surface, with cement; cutting off casing strings four (4) feet below surface. Pits will be filled and leveled and area reseeded to B.L.M. specifications.

Tests indicate gas production non-commercial.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Engineer

DATE Aug. 9, 1977

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED


DATE

AUG 11 1977

*See Instructions on Reverse Side

U. S. GEOLOGICAL SURVEY

790 FSL, 1850 FWL
 Section 6, T26N, R12W
 Elevation 5970



MERRION~BAYLESS

PROPOSED ABANDONED PROFILE

Chaco #8

SCALE N/A
 DATE 8-9-77
 DRAWN BY SSD
 CHECKED

DATE OF REVISION
 C8-2-77