Submit 3 Copies
to Appropriate
District Office

State of New Mexico

to Appropriate District Office	Energy, Minerals and Natural Resources Department			Form C-103 Revised 1-1-89			
	ON CONCEDED MARCH	tancing data	WALL ADINO				
<u>DISTRICT I</u> P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION D	NAPROM	WELL API NO.	30-045-22575			
	2040 Pacheco St.		5. Indicate Type of				
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, NM 87505		5. Indicate Type of	STATE X	FEE		
DISTRICT II			6. State Oil & Ga	s Lease No.			
1000 Rio Brazos Rd., Aztec, NM 8741	0	<u> </u>		LG-3735			
SUNDRY NOTIC	ES AND REPORTS ON W	VELLS					
	ORPOSALS TO DRILL OR TO DEEPEN OR I		7. Lease Name or	Unit Agreement N	ame		
DIFFERENT RES	ERVOIR. USE "APPLICATION FOR PERMIT						
	(C-101) FOR SUCH PROPOSALS)		STATE				
1. Type of We 1:			Jimb				
OIL GAS WELL X	OTHER						
2. Name of Operator			8. Well No.				
Coleman Oil & Gas, Inc.			#1	77'1 1 4			
3. Address of Operator			9. Pool name or V	wildcat and Coal & WAV	W Pictured (Cliffs	
P.O. Drawer 3337			Dasin Fruitia	mu Coai & WAY	T I ICIUICU (
4. Well Location	TOO DIE TO NODTH	I in a and	790	Feet From The	EAST	Line	
Unit Letter A	790 Feet From The NORTH						
Section 2	Township 26N Range 13W	V	NMPM	Sa	n Juan	County	
	10. Elevation (Show wheth	er DF, RKB, RT, G	iR, etc.)				
	6006						
Check	k Appropriate Box to Indica	te Nature of N	Notice, Report,	or Other Data	1		
NOTICE OF I	INTENTION TO:		SUBSEQUEN	IT REPORT (OF:		
	. –	REMEDIAL WOR		ALTERING CAS	ING	П	
PERFORM REMEDIAL WORK	PLUG AND ABANDON		_	•			
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DR	ILLING OPNS.	PLUG AND ABA	NDONMENT		
PULL OR ALTER CASING		CASING TEST A	ND CEMENT JOB]			
OTHER: See Below	x	OTHER: See B	elow	<u></u>		X	
	tions (Clearly state all pertinent details, and give p	ertinent date, including e	stimated date of starting ar	ny proposed			
work) SEE RULE 1103.	ions (Clearly state an permient actuals, and group	· · · · · · · · · · · · · · · · · · ·					
Replacement well State #	1R has been Drilled and Com	pleted.					
The State #1 was shut in	and piping disconnected from	the production	separator as of	April 6, 2001	at 7:00 A	M.	
The State #1 was shut in	onitor the State #1R for six m	onths to a vear	nrior to pluggir	g the State #1.			
Request permission to me	Shifter the State #1K for six in	onins to a year	prior to pre-88	8			
V	1 0 1 202						
* Confly Wis	th Kule 203						
I hereby cer ify that the information	n above is true and complete to the best of my	knowledge and belief.					
SIGNATURE	had Illano	TITLE	ENGINEER	DATE	04/20	/01	
	MICHAEL T. HANSON			TELEPHONE NO.	505-327	-7160	
TYPE OR PRINT NAME IV	HOHELD I. HEROOT.						
(This space for State Use)	HED BY CHAPLE T. PERWIN	-	All 4 A 4 6 1165	TOB 8157 55	MAY 1	L 2001	
	The set of the second s	TITLE	OIL & GAS INSPEC	IUK, PISI. #3 Date	* ** ** **		
APPROVED BY							

