4-USGS (Farm)	ington, i with i Tenneco	1.1.1.9	
form 1-331	UNITED STATES DEPARTMENT OF THE INTER	Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESCENATION AND SERIAL NO. NM 26354	
	GEOLOGICAL SURVEY		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	RY NOTICES AND REPORTS orm for proposals to drill or to deepen or plug use "APPLICATION FOR PERMIT—" for such	· hack to a different reservoir.	/signature 10 (20 m)
OIL GAS ELL WELL	OTHER		7. UNIT AGREEMENT NAME TO THE STATE OF THE S
2. NAME OF OPERATOR Dugan Production Corp.			Designated Hitter
Dugan Production Corp. 3. Address of Operator			9. WELL NO.
P. O. Box 234, Farmington, NM 87401			#2 ====================================
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface			NIPP Pictured Cliffs
790' FSL - 790' FWL			11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA
			Sec 27/2 126N, R12W
14. PERMIT NO.	15. ELEVATIONS (Show whether	DF, RT, GR, etc.)	12. COUNTY-OR: PARISH 13. STAYE
	6132' GR		San Juan NM
16.	Check Appropriate Box To Indicate	Nature of Notice, Report, or	Other Data book of the same
,	OTICE OF INTENTION TO:	BUBSEC	CENT REPORTS OF ELL STATE OF EL
TEST WATER SHUT-OF	PULL OR ALTER CASING	WATER SHUT-OFF	FREPAIRING WELL.
FRACTURE TREAT	MULTIPLE COMPLETE	PRACTURE TREATMENT SHOOTING OR ACIDIZING	SABANDON MENT
SHOOT OR ACIDIZE REPAIR WELL:	ABANDON* CHANGE PLANS	(Other)	s of multiple-completion on Well
(Other)		Completion or Recom	pletion Report and Log form.)
17. DESCRIBE PROPOSED OR proposed work. If nent to this work.) •	COMPLETED OPERATIONS (Clearly state all pertix well is directionally drilled, give subsurface k	peations and measured and true verti	cal depths for all markers: and zones pertly to vitant and the markers and zones pertly to per subtract the perturbation of the markers and zones pertly to vitant an
•	•	•	
12-19-77	Moved in and rigged up Mo @ 10:00 a.m. Drlg to 35' 34.40' set @ 35' GR. Cem 9-18-77.	. Ran 1 jt 5-1/2" OD	14# ST&C csg. TE
12-24-77	Ran 39 jts 2-7/8" OD 6.4# TE 1224.33' set @ 1224' GI Had good mud returns and preflushed hole w/100 gals	R. Hydro tested to 4(recip. pipe during cen s mud sweep. Cemented	000 psi - OK menting operations. N w/75 sx 2%
	Lodense w/l/4# cello flake flake/sx. Bumped plug w/l Circulated 2 bbls cement.	1750 psi. Shut In.	neat w/1/4# cello POB 2:45 p.m. 12-23-77.
		JAN 4 1978 OIL CON. COM DIST. 3	total in the property of the policy of the p
SIGNED A.A	the foregoing is true and correct TITLE	Petroleum Engineer	DĂTM 12-28-77
Thoma (This space for Fede	s A Dugan eral or State fffice use)		Const. Prop. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.
APPROVED BYCONDITIONS OF A	PPROVAL, IF ANY:		DAME TO THE TERMS