

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Estimate No. 42
5. LEASE DESIGNATION AND SERIAL NO.

NM 1336

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Monticello

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

WAW - Pictured Cliffs

11. SEC. T. R. M. OR BLK. AND SURVEY OR AREA

Sec 3, T26N, R13W

12. COUNTY OR PARISH

San Juan

13. STATE

NM

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Dugan Production Corp.

3. ADDRESS OF OPERATOR

Box 234, Farmington, NM 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)
At surface

1190' FNL - 1450' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6201' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENTS*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROMISED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

(OVER)



18. I hereby certify that the foregoing is true and correct

SIGNED

Thomas A. Dugan
Thomas A. Dugan

TITLE Petroleum Engineer

DATE 9-9-77

(This space for Federal or State only use)

APPROVED

CONDITIONS OF APPROVAL, IF ANY:

SEP 12 1977

E. J. McGRATH

DISTRICT ENGINEER

*See Instructions on Reverse Side

8-23-77

Moved in and rigged up Morrow Drilling Company rig.
Spudded 7-7/8" hole @ 2:00 PM 8-22-77. Drilled to
37' and set 1 jt 5-1/2" OD 14# 8R ST&C csg. TE 36.90'
set @ 37' CR. Cemented to surface w/5 sx. Job complete
4:00 PM 8-22-77. WOC.

8-25-77

Depth 550'. Drill pipe stuck in hole. Rig shut down.
Crew quit.

8-26-77

Depth 550'. Unable to work pipe out of hole. Pusher
cussed out crew. Driller said, "...to hell with you...
I quit!"

8-27-77 til 9-7-77

Looking for new crew.

Plan to plug and abandon this well as follows:

Spot 10 sx cement 300-200' *(at top of fish)*

Spot 10 sx cement 100' to surface

Cut off surface casing 4' below ground level

Clean up location and abandon well.