

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

N00-C-14-20-2941

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Pinabete-Navajo 32-2

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 2, T-26-N, R-15-W

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

1.

OIL ☒ GAS ☐  
WELL WELL OTHER

2. NAME OF OPERATOR

Champlin Petroleum Company

3. ADDRESS OF OPERATOR

P.O. Box 1257, Englewood, Colorado 80150

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

SW NE ~~2055~~ FNL, 1980' FEL Sec. 2

1980

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

5862' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*


(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

Verbal permission received 12/28/77 from L.L. Seelinger, U.S.G.S., Farmington, New Mexico, to plug and abandon well as follows:

1. TD(4750') to 440' (350' plug)(113 sacks) Gallup Top 4463'
2. 3590' to 3390' (200' plug)(92 sacks) Pt. Lookout Top 3465'
3. 1025' to 850' (175' plug)(56 sacks) Picture Cliffs Top 950'
4. 320' to 273' (47' plug) (15 sacks) Base of Surface Pipe 300'
5. 30' to 0' (30' plug) (10 sacks) Top of Surface Pipe
6. Dry hole marker showing well name, location and Lease Number.

Well plugged and abandoned 12/30/77.



18. I hereby certify that the foregoing is true and correct

SIGNED

J.N. McGirl

TITLE

District Drilling and  
Production Superintendent

DATE

1/4/78

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

RECEIVED

JAN 9 1978

U.S. Geological Survey,  
Farmington, N.M.

\*See Instructions on Reverse Side