

Form 9-331  
(May 1963)UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE\*  
(Other instructions on reverse side)Form approved.  
Budget Bureau No. 42-R1424.

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. NM 17781	
2. NAME OF OPERATOR Dugan Production Corp.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR Box 234, Farmington, NM 87401		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1190' FNL - 1000' FWL		8. FARM OR LEASE NAME Paul Revere	
14. PERMIT NO.		9. WELL NO. #203	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 6212' GR		10. FIELD AND POOL, OR WILDCAT Wildcat	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 22 T26N R13W	
		12. COUNTY OR PARISH San Juan	
		13. STATE NM	

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

## SUBSEQUENT REPORT OF:

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

REPAIRING WELL

SHOOT OR ACIDIZE

ABANDON\*

SHOOTING OR ACIDIZING

ALTERING CASING

REPAIR WELL

CHANGE PLANS

(Other) Status

ABANDONMENT\*

(Other)


(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

## 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

9-8-82

MI & RU Hinson Service Company Inc. and prepare to swab 2 7/8" casing. SICP 10 psi. Fluid level first swab run at 500' above perfs. Second swab run recovered 200' heavy water cut with gas. Dropped one soap stick. Waited 20 mins and made third swab run. No sign of fluid or gas entry. Shut well in.

This well currently under evaluation.



## 18. I hereby certify that the foregoing is true and correct

SIGNED

JIM L. Jacobs

TITLE

Geologist

DATE

9-22-82

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

DATE

ACCEPTED FOR RECORD

SEP 27 1982

\*See Instructions on Reverse Side

NMCC

FARMINGTON DISTRICT

RV