5. LEASE

UNITED STATES DEPARTMENT OF THE INTERIOR

| DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY | SF 281120-A 6. IF INDIAN, ALLOTTEE OR TRIBE NAME |
|---|--|
| SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.) | 7. UNIT AGREEMENT NAME |
| 1. oil gas well other Dry 2. NAME OF OPERATOR Bedford, Inc. 3. ADDRESS OF OPERATOR F. O. Box 255, Farmington, Nii 37401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 1450' fn1, 1450' fel AT TOP PROD. INTERVAL: AT TOTAL DEPTH: Same 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA | 8. FARM OR LEASE NAME Rati 9. WELL NO. 1-A 10. FIELD OR WILDCAT NAME WAM Fruitland - P.C. 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA SG-T2CH-R12H. H. H. P. H. 12. COUNTY OR PARISH 13. STATE San Juan Hew Hexico 14. API NO. 30-045-23339 15. ELEVATIONS (SHOW DF, KDB, AND WD) |
| REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF | (NOTE: Report results of multiple completion or zone change on Form 9-330.) all pertinent details, and give pertinent dates, |
| Mov. 15, 1979 - Tested well - no gas, Nov. 16, 1979 - Rigged up cementing true cement slurry into 2 7/8", pressupsi while pumping. Filled tubing dry hole marker over 2 7/8 stub and leveled location. | no SI pressure. uck, pumped 7½ sacks neature build-up slowly to 350 |
| Subsurface Safety Valve: Manu. and Type | |
| (This space for Federal or State office | e use) |
| APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY: | DATE |