Form 9-331 Dec. 1973

## UNITED STATES

Form /	approved	f.	
Budget	Bureau	No.	42-R1424

DEDINTIFUE OF THE INTERIOR	5. LEASE
DEPARTMENT OF THE INTERIOR	NM 33032 .
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use Form 9–331-C for such proposals.)	7. UNIT AGREEMENT NAME
	8. FARM OR LEASE NAME Sunshine
1. oil gas other dry hole	9. WELL NO.
2. NAME OF OPERATOR	#1
Dugan Production: Corp.  3. ADDRESS OF OPERATOR	10. FIELD OR WILDCAT NAME WAW Fruitland PC
Box 208, Farmington, NM 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	AREA Sec 32 T26N R13W
AT SURFACE: 800' FNL - 790' FEL	12. COUNTY OR PARISH 13. STATE
AT TOTAL DEPTH:	San Juan NM
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	
	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6331' -GR
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
FRACTURE TREAT	
SHOOT OR ACIDIZE  REPAIR WELL  T	
PULL OR ALTER CASING [	(NOTE: Report results of multiple completion or zone change on Form 9-330)
MULTIPLE COMPLETE	
ABANDON*	
(other)	
<ul> <li>17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is dimeasured and true vertical depths for all markers and zones pertinen August 6, 1979         Plugged and abandoned well as follows:         <ol> <li>Spotted 200' cement plug from TD (1506')</li> </ol> </li> </ul>	rectionally drilled, give subsurface locations and to this work.)*
2. Spotted 300' cement plug from 300' to se	urface.
3. Cut off 5-1/2" csg 4' below ground leve	
4. Filled pits and leveled location.	AUG 1 7 1979
Subsurface Safety Valve: Manu. and Type	Set Set
18. I hereby certify that the foregping is true and correct	
	DATE8-14-79
(This space for Federal or State office	ce use)
APPROVED BY TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:	