MERRION & BAYLESS

Chaco Ltd. #2 NE/4 Section 1, T26N, R13W San Juan County, New Mexico

SLOPE TESTS

Depth	Hole <u>Deviation</u>
155 ft.	.20
875 ft.	.4 ^O
1285 ft.	•4 ^o



State of New Mexico)) ss County of San Juan)
I, Robert L. Bayless, being first duly sworn, depose and state that the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.
Subscribed and sworn before me this 30th day of Ail, 1980.

My Commission Expires 09-20-80