UNITED STATES						
DEPARTMENT OF THE INTERIOR						
GEOLOGICAL SURVEY						

5. LEA	SE	: 5 =	ί	583
sf	078899		-	
	IDIAAL ALLA	3TTFF (- TD:	DC 41445

	UNITED STATES	5. LEASE		
DEPA	ARTMENT OF THE INTERIOR	SF 078899		
	GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
	TIGES AND DEDODES ON WELLS	7. UNIT AGREEMENT NAME		
SUNDRY NO	TICES AND REPORTS ON WELLS	【 ■ 「 「 「 「 」 「 」 「 」 「 」 「 」 「 」 「 」 「 」		
(Do not use this form for reservoir 11se Form 9-33)	proposals to drill or to deepen or plug back to a different 1–C for such proposals.)	8. FARM OR LEASE NAME 7 8 2 4		
		8. FARM OR LEASE NAME OF SERVICE BLACKFOCK DE SERVICE SERVICE		
1. oil gas	⊠ other			
well Well	VIII.	-l 'TEX_		
2. NAME OF OPER	ATOR			
	y Merrion & Robert L. Bayles	s 10. FIELD OR WILDCAT NAME Basin Dakota ។ , ទីនិទី		
3. ADDRESS OF OF				
	507, Farmington, NM 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR		
4. LOCATION OF W	ELL (REPORT LOCATION CLEARLY. See space 17	AREA ELEGE		
below.)		Section 20, T26N, R11W		
AT SURFACE:	790 FSL & 1650 FWL	12. COUNTY OR PARISH 13. STATE		
AT TOP PROD. INTERVAL:		San Juan New Mexico		
AT TOTAL DEPTH	1:	14. API NO. HE HE HE TO THE HE TO THE HE H		
16. CHECK APPROP	RIATE BOX TO INDICATE NATURE OF NOTICE,			
REPORT, OR OT	HER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)		
		6155 GL ੋਂ 6169 KB ਹੈ ਹੈ ਹ		
REQUEST FOR APPR	OVAL TO: SUBSEQUENT REPORT OF:			
TEST WATER SHUT-	OFF 🔲 💹			
FRACTURE TREAT	님 님	로운전화 공기원 속소		
SHOOT OR ACIDIZE	님 님	<u> </u>		
REPAIR WELL PULL OR ALTER CA		(NOTE: Report results of multiple completion or zone change on Form 9–330.) = 1 = 1 = 2		
MULTIPLE COMPLET		ည ခို့ချစ်သည် ရှိသို့မြို့ တ		
CHANGE ZONES		그 그 그는 그를 가는 그를 가는 그를 가는 것이 되었다.		
ABANDON*				
(other)		is it in the property of the p		
17. DESCRIBE PROF	POSED OR COMPLETED OPERATIONS (Clearly stated date of starting any proposed work. If well is a	te all pertinent details, and give pertinent dates,		
measured and tr	ue vertical depths for all markers and zones pertine	nt to this work.)* জু টু টু ভু জু টু এই টু		
10-18-79	Spudded surface hole at 4:3	0 PM. Drilled to 1897 K.B.		
10 10 75	Pan 4 its 8-5/8" 24# K-5	5 casing, set at 184 K.B. and		
	compared with 165 sy class	A cement w/ 2% CACL2. Circulated		
	coment to ground surface by	t cement fell back down hole		
	cement to ground surface be			
10 10 70	13 ft.	ent and re-cemented w/ 50 sx		
10-19-79	Ran I tubing to top or ten	talled POP Tested surface		
	Class A With 3% CACL2. Ins	talled BOP. Tested surface		
		8 hrs after first cement job.		
	Held okay.	지수는 사람들은 사람들이 함께 사람들이 되는 것이다.		
		고려진상은 학문 원활과원		
		# 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
Subsurface Safety Va	Ive: Manu. and Type	Set @ Ft.		
11/	i			

Subsurface Safety Valve: Manu. and Type		Set	@ 🚊 📜 Ft.
18. I hereby certify that the foregoing is to			Copper Co
SIGNED Deary Menon		DATE November	: 30 ½ ½ 979
SIGNED	(This space for Federal or State office use)		<u> </u>

*See Instructions on Reverse Side

JAMES F. SIMS DISTRICT OIL & GAS SUPERVISOR