Form Approved. Budget Bureau No. 42-R1424

UNITED STATES

UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	SF - 078384
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	N/A
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME N/A
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME
1 oil mag	Newsom "B"
1. oil gas well other	9. WELL NO.
2. NAME OF OPERATOR	14E
Supron Energy Corp. c/o John H. Hill, et al.	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR Kysar Building, Suite 020	Basin Dákota
300 W. Arrington, Farmington, New Mexico 8740	111. SEC., I., R., M., OR BLK. AND SURVEY OR AREA
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	Sec. 9 T26N R8W
AT SURFACE: 1700' FSL & 1765' FEL (NW SE)	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	San Juan New Mexico
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6498' GR
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	0430 un
TEST WATER SHUT-OFF	
FRACTURE TREAT	
SHOOT OR ACIDIZE	(NOTE: Report results of multiple completion grade
SHOOT OR ACIDIZE REPAIR WELL REPAIR CASING RECE	(NOTE: Report results of multiple completion of idea (NOTE: Report results of idea
MULTIPLE COMPLETE	29 1900
<u> </u>	C111.3
ABANDON* U. S. GEOLS (other)	OCICAL SURVEY OTON, N. M. COM. DIST. 3
L. Comment	- 3 /
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is constant of the control of the	lirectionally drilled, give subsurface locations and
measured and true vertical depths for all markers and zones pertine	nt to this work.)*
1. Spudded 12½" hole, to 330' at 6:00 A.M.,	
2. Ran 7 joints (317') of new 8 5/8", 24# S	I&C casing.
 Set and cemented at 317'. Cemented with 250 sacks Class B cement, 8 	P sacks Calcium Chlonida
 Cemented with 250 sacks Class B cement, 8 and 3 sacks flo-cele. 	sacks carcium chiloride
5. Plug down at 11:15 A.M., 6/1/80.	
6. Circulation good, cemented to surface.	
7. Test water shut off with 900# thru 900 Se	eries Gardner-Denver
Blow-out Preventer	
Subsurface Safety Valve: Manu. and Type	Set @ Ft
18. I hereby certify that the foregoing is true and correct	687 : 5 (888
Exploration and Dev	velopment OCT 1 5 1380
SIGNED WMMUN V. WMMUN TITLE SUperIntende	III. DATE
(This space for Federal or State or	ffice use)
APPROVED BY TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:	

*See Instructions on Reverse Side