

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Form Approved.
Budget Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other ☐

2. NAME OF OPERATOR
Southern Union Exploration Company

3. ADDRESS OF OPERATOR
1217 Main Street, Dallas, Texas 75202

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 810' FSL & 1520' FEL

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) ☐

SUBSEQUENT REPORT OF:

☐
☐
☐
☐
☐
☐
☐
☒

5. LEASE

NM 33030

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

SX Federal 25

9. WELL NO.

1

10. FIELD OR WILDCAT NAME

Picture Cliffs

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec 25, T26N, R13W

12. COUNTY OR PARISH

San Juan

13. STATE

New Mexico

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
6138' GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- 1) Well was spudded on 11/7/79 using an 8 3/4" bit.
- 2) Surface hole was drilled to 97' and 7" casing (95') was run and cemented to grass roots.
- 3) Surface casing was tested to 1000# for 30' with no leaks.
- 4) Surface casing was drilled out from under with 5" bit to a TD of 1304' and logged.
- 5) No production zones were found and the Commission was called and a request granted to plug and abandon on 11/13/79.
- 6) 11/14/79 well was plugged as follows:

A 25 sk plug from 1240' to 1016' and a 25 sk plug from 236' to surface.

7) Location has been cleaned up.

Subsurface Safety Valve: Manu. and Type

Set @

18. I hereby certify that the foregoing is true and correct

SIGNED James F. Sims TITLE Drilling & Production Eng. DATE January 22, 1982

(This space for Federal or State office use)

APPROVED BY Blw CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

NMOCC

APPROVED

JUN 22 1982

For JAMES F. SIMS
DISTRICT ENGINEER

